



Corporate Office
 17522 Bothell Way Northeast
 Bothell, Washington 98011
 425.415.0551
 www.riley-group.com

Project No: 2019-134
Report No: 140
RGI rep: Collin McCracken
Date: 10/1/2021 Friday
Page No. 1 of 1
Subject: Subgrade Observations Lot 28
Contractor: _____
Superintendent _____
Visitors: _____
Weather: Sunny

Permit No: BLD20-00238
Project: Mallard Pointe
Location: SE 43rd Way and E Lk Sammamish SE, Issaquah
Client Name: Steve Burnstead Construction LLC
& Address: 11980 Northeast 24th Street, Suite 200
Bellevue, WA 98005

OBSERVATIONS:

As requested, a Riley Group representative visited the site today to observe and evaluate the following:

Contractor has excavated and poured the foundation for lot 28. Subgrade was tested around the existing foundation with a ½” steel tipped T-probe, and yielded less than 1”, with some saturation observed at the surface from form removal workers. The subgrade is observed to be in firm and unyielding conditions suitable for the design bearing pressure.

RGI Rep sign: Collin McCracken Copies To: _____

Reviewed by Kristina Weller _____